

AAR M1003 Certified

REMANUFACTURING GE AIR TO AIR COOLERS



Proprietary Remanufacturing Process:

- Air to Air coolers are remanufactured by first completely cleaning the unit by pressure washing & internally flushing the core.
- Detailed inspection of the unit for leaks while applying pressure to the core.
- All threaded holes are checked & repaired as needed.
- All gasket surfaces are cleaned and resurfaced
- ♦ A final pressure check is done.
- The cooler is then completely dried, wrapped and skidded for shipment.

Represented by JMA Railroad Supply 835 E 10th Street, Seymour, IN 47274 Phone: (812) 522-7200 Fax: (812) 522-1150 Email: jmasales@jmasales.com

Repair & Return pricing is available on ALL Air to Air Coolers

> P/N'S : 84A213197ABP1 84A213197ABP2